

Squeaking noise that occurs when engine is suddenly accelerated

V-belt loosened or deteriorated